Material Safety Data Sheet

(Approved by US Department of Labor "Essentially Similar to form OSHA-20)

Emergency Telephone:

502 267 7717

Flexible Materials Inc.

11209 Electron Drive Louisville, KY 40299

Date:	August 31,	1996

	Section 1 —	Identification		
Product Name 5 mil & 10 mil backe Tradename Woodtrim	d edgebanding , E Z Edge	Chemical Name N/A DOT Hazard Class N/A	J	
Section 2 —— Important Components				
Genuine wood venee impregnated cellulos		Permissable Exposure Concentration Not regulated	<u>n</u>	
	Section 3	Physical Data		
Boiling Point Vapor Pressure Vapor Density Solubility in Water Appearance and Odor:	N/A N/A N/A N/A Slight if any	Specific Gravity Percent Volatile Evaporation Rate	N/A N/A N/A	
Section 4 —— Fire and Explosion Data				
Flammability Classification Will support combust	ion	Flash Point N/A		
Extinguishing Media				
Water, Foam, CO2				
Unusual Fire and Explosion Hazards				
None known				
Special Fire Fighting Procedures				
Firefighters should wear self—contained breathing apparatus to avoid inhalation of smoke or vapors.				
This information is furnished without warranty representation, inducement of license of any kind, except that it is accurate to the best of Flexible Materials Inc.'s knowledge, or obtained from sources believed by Flexible Materials Inc. to be accurate, and Flexible Materials Inc. does not assume any legal responsibility for use or reliance upon same. Customers are encouraged to conduct their own tests.				
Before using any product, read its labe	:L		A:\5 10EDGE.WK1	

Section 5 F	ealth Hazard Data		
Eyes, skin, nose & throat irritant upon overexposure. Avoid continued exposure if indicated. Emergency and First Aid Proceedures			
Wear gloves, goggles and approved masks. Flush skin and eyes with clean water and consult a doctor.			
Section 6 ——	Reactivity Data		
Stable			
Hazardous Decomposition Products Smoke and fire if ignited. Acrid and cholapproved self contained breathing apparation Will not occur	king fumes may also be liberated. Wear stus to fight fire.		
Conditions to avoid Open flame and ignition			
Section 7 —— Spill or Leak Procedures			
Sweep up and place in closed container. Wear a dust mask if dust is created.	Incinerate in approved incinerator or dispose of in a chemical dump in accordance with local state and federal reg		
Section 8 —— Special	Protection Information		
Dust masks recommended when machining.			
Ventilation Ensure adequate ventilation			
Protective Gloves Leather gloves recommended	Eye Protection Goggles recommended		
Other Protective Equipment			
Section 9 —— Sp	ecial Precautions		
Store in cool dry location			
Consult application instructions or labels prior to using this material			

4 . 4