

11/03

Glue

MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP: JULY 10, 1998

SECTION I				
MANUFACTURER'S NAME:	SOUTHERN RESIN, INC.			
STREET ADDRESS:	3440 DENTON ROAD THOMASVILLE, NC 27360			
EMERGENCY TELEPHONE #	910-475-1348	MANUFACTURER'S CODE IDENTIFICATION		
PRODUCT CLASS:	VINYL COPOLYMER RESIN EMULSION ADHESIVE	PB-3250		
TRADE NAME:	PRO-BOND			
SECTION II - HAZARDOUS INGREDIENTS				
INGREDIENT	PERCENT	EXPOSURE LIMITS	LEL	VAPOR PRESSURE
VINYL ACETATE (CAS #108-05-4)	AVG. = 0.4			
FORMALDEHYDE (CAS #50-00-0)	<0.1			
SECTION III - PHYSICAL DATA				
BOILING RANGE: 98° - 103°C. (208° - 217°F.)	VAPOR DENSITY _ HEAVIER X LIGHTER THAN AIR			
EVAPORATION RATE _ FASTER X SLOWER THAN ETHER	PERCENT VOLATILE	WEIGHT PER		
	BY VOLUME: 52%	GALLON:	9.1 LBS.	
SECTION IV - FIRE AND EXPLOSION HAZARD DATA				
DOT CATEGORY: ADHESIVE, NOIBN	FLASH POINT N/A		LEL N/A	
EXTINGUISHING MEDIA: N/A				
UNUSUAL FIRE AND EXPLOSION HAZARDS: N/A				
SPECIAL FIRE FIGHTING PROCEDURES: N/A				

The information contained herein is furnished without warranty of any kind, except that it is accurate to the best knowledge of the manufacturer or obtained from sources considered to be accurate and the manufacturer does not assume any legal responsibility for the use or reliance upon same. Employees should use this information along with their own determinations to assure proper use and the safety and health of employees.

SECTION V – HEALTH HAZARD DATA

EXPOSURE LIMITS: N/A

EFFECTS OF OVEREXPOSURE:

Irritation of eyes and upper respiratory passages; skin irritation.

EMERGENCY AND FIRST AID PROCEDURES:

INHALATION: Remove to fresh air.

SKIN CONTACT: Flush with water.

EYE CONTACT: Flush with large amounts of water, contact physician. Get medical attention for unusual exposures.

SECTION VI – REACTIVITY DATA

STABILITY UNSTABLE STABLE

CONDITIONS TO AVOID: N/A

INCOMPATIBILITY (Materials to avoid) N/A

HAZARDOUS DECOMPOSITION PRODUCTS: N/A

HAZARDOUS POLYMERIZATION: MAY OCCUR WILL NOT OCCUR

CONDITIONS TO AVOID: N/A

SECTION VII – SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Clean up into suitable container. Mop up, flush with water.

WASTE DISPOSAL METHOD: In accordance with federal and/or state regulations for solid waste disposal.

SECTION VIII – SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION: Not normally required.

VENTILATION: Normal ventilation generally adequate.

PROTECTIVE EQUIPMENT OF CLOTHING REQUIRED: Rubber, neoprene, or plastic recommended.

EYE PROTECTION: Goggles or safety glasses to avoid splashes.

OTHER PROTECTIVE EQUIPMENT: None required.

SECTION IX – SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep from freezing.

OTHER PRECAUTIONS: Store at room temperature. Keep containers closed to prevent drying out. Avoid contamination. Do not mix with other adhesives.