

MATERIAL SAFETY DATA SHEET

Rboard®

MANUFACTURER: Atlas Roofing Corporation
ADDRESS: 2000 River Edge Parkway

Suite 800

Atlanta GA 30328

PHONE : Call one of the following numbers for the location closest to you.

Hours 8:00 AM to 5:00 PM (respective time zone)

 Camp Hill, Pennsylvania
 800-688-1476

 East Moline, Illinois
 800-677-1476

 LaGrange, Georgia
 800-955-1476

 Northglenn, Colorado
 800-288-1476

 Phoenix, Arizona
 800-477-1476

 Diboll, Texas
 800-766-1476

 Etobicoke, Ontario, Canada
 888-647-1476

DATE OF

PREPARATION: January 1, 2005

PREPARED BY : Environment and Health Officer

PRODUCT NAME: Rboard[®] Insulation

SECTION 1 - COMPONENT DATA

HAZARDOUS INGREDIENTS

COMMON NAME	CHEMICAL NAME	PERCENT (approx.)	C.A.S. NUMBER
Polyisocyanurate Foam	Same	97	None
Pentane	Same	2	109-66-0
Fiberglass	Fibrous Glass	1	65997-17-3

SECTION 2 - PHYSICAL DATA

Vapor Density (Air = 1)

PROPERTY PROPERTY

Boiling Point (° F) : NA* Specific Gravity (H₂0=1) : ND**

Melting Point : NA Solubility In Water : Insoluble

Vapor Pressure (mmHg @ 20° C) NA Evaporative Rate (Ethyl Ether = 1): NA

NA

NA

Percent Volatile By Volume: NA Appearance And Odor : White or cream colored solid

with a coated glass mat facing

and with no odor

*NA = Not Applicable **ND = Not Determined

SECTION 3 - FIRE & EXPLOSION HAZARD DATA

Flash Point (° F) : NA Method Used : NA

Flammability Limits : NA

LEL: NA UEL: NA

Auto-Ignition Temperature (° F) : NA

Extinguishing Media : CO₂, Dry Chemical, Water Spray

Special Fire Fighting Instructions : Self contained breathing apparatus

Unusual Fire And Explosion Hazards: This product will burn and should not be left exposed. Under certain

fire conditions, combustible gases can be generated creating rapidly spreading, high intensity flames and dense, black smoke.

SECTION 4 - REACTIVITY DATA

Stability (Conditions to Avoid) : Stable, avoid sources of ignition

Incompatibility (Materials to Avoid) : Acetone, methyl ethyl ketone, tetrahydrofuran,

chlorine, chloroform, hydrogen peroxide, ethylene dichloride, dimethyl sulfoxide, and dimethyl formamide.

Hazardous Decomposition Products : Primarily CO, CO₂. Some HCN possible

under certain conditions.

Hazardous Polymerization : Will not occur

SECTION 5 - HEALTH HAZARD DATA

Primary Route(s) of Entry : Inhalation

Health Hazards (Acute and Chronic) :

INHALATION

For Fibrous Glass

Acute : Mechanical irritation of the mouth, nose and throat.

Chronic : No chronic health effects are known to be associated with exposure to

continuous filament fiberglass. Results from epidemiological studies have not shown any increase in respiratory disease or cancer. The International Agency for Research on Cancer (IARC) has classified

continuous filament fiberglass "Not Classifiable as to be Carcinogenicity to Humans" (Group 3; i.e., IARC-3).

For Polyisocyanurate Foam

Acute : Dust will cause respiratory tract irritation.

Chronic: There is no evidence that polyisocyanurate foam dust causes

disease in humans.

SKIN CONTACT

For Fibrous Glass and Polyisocyanurate Foam

Acute : Transient mechanical irritation.

Chronic: None known.

EYE CONTACT

For Fibrous Glass and Polyisocyanurate Foam

Acute : Mechanical irritation.

Chronic: None known.

Signs and Symptoms of Exposure

Mechanical irritation of the eyes, skin and respiratory tract.

Medical Conditions Generally Aggravated By Exposure

Any condition generally aggravated by mechanical irritants in the air or on the skin.

Exposure Limits

Hazardous Ingredients	OSHA PEL	ACGIH TLV	Other Recommended
	(mg/M³)	(mg/M³)	(Source)
Polyisocyanurate Foam (as nuisance dust)	15 mg/M ³	10 mg/M ³	None
Pentane	1000 ppm TWA	600 ppm TWA	1500 ppm IDLH (NIOSH)
Fibrous Glass (respirable nuisance dust)	5 mg/M ³	10 mg/M ³	3 x 10 ⁶ fibers/M ³ (NIOSH)

Carcinogenicity

Hazardous Ingredients	NTP Listed	IARC Listed	OSHA Regulated
Polyisocyanurate Foam	No	No	No
Pentane	No	No	No
Fibrous Glass	No	No	No

SECTION 6 - EMERGENCY AND FIRST-AID PROCEDURES

Inhalation : None required.

Skin : Wash with soap and cool running water.

Eyes : Flush with running water for at least 15 minutes.

SECTION 7 - SPECIAL HANDLING AND STORAGE INFORMATION

Installation Procedure : Cutting of product should be done with a serrated type knife or saw

(i.e. gypsum wallboard or keyhole). The use of rotary powered saws is not recommended, as the original continuous filament fibers in the facings are of non-respirable size and the use of powered saws may

create smaller fibers and cause them to become airborne.

Ventilation : Ambient. Store in a dry, well ventilated area. Assure storage

containers or areas and shipping containers are adequately

ventilated.

Respiratory Protection : If irritation occurs or TLV is exceeded, use a respirator such as

3M Model 8271, Model 8210, or equivalent for protection against

nuisance dusts.

Protective Clothing : If excessive dust is generated during cutting operations, wear

long sleeved shirt, loose fitting clothing, long pants and gloves,

to reduce irritation.

Eye Protection : Goggles or safety glasses with side shields are recommended.

Work / Hygienic Practices : Exposed skin areas should be washed with soap and cool water after

working with product. Clothing should be laundered separately from other clothes. Handle product using good industrial hygiene and safety practices. Avoid unnecessary dust exposures when cutting or

abrading by using adequate local or general ventilation.

SECTION 8 - SPILL, LEAK & DISPOSAL PROCEDURES

Action To Take For Spills (Use Appropriate Safety Equipment):

NA

Waste Disposal Method :

Dispose in accordance with federal, state and local regulations.

The primary method of disposal is in a municipal or industrial landfill.

EPA Hazardous Waste Number : NA

This material is not regulated under the "RCRA" hazardous waste regulations.

SECTION 9 - SPECIAL PRECAUTIONS / ADDITIONAL INFORMATION

Precautions To Be Taken In Handling And Storage : None

Department of Transportation Information

Hazardous Material Proper Shipping Name : Not Regulated by D.O.T.

Hazard Class : NA UN Identification Number : None

Additional Information : None

Prepared by: Larry Overstreet (KH)

Environment and Health Officer Atlas Roofing Corporation